

## APPENDIX B

**Standard PPE worn with all tools and equipment. FRC(If Host Facility Requires), Steel Toe Boots w/defined heel, Hard Hats with Goggles (If Host Facility Requires) and Safety Glasses. If prolonged kneeling is required for your job task, knee pads will be required.**

Tools or Equipment	PPE Required
Vehicle/Industrial Batterys ➡	Face Shield, Gloves
Gas/Diesel Equipment ➡	Hearing Protection
Concrete Vibrator ➡	Gloves, Hearing Protection
Soil Pick ➡	Gloves, Hearing Protection, Face Shield
Jack Hammers ➡	Gloves, Double Hearing Protection, Face Shield, NIOSH Dust Mask
Bush Hammers ➡	Gloves, Hearing Protection, Face Shield,
Chain Saw ➡	Gloves, Hearing Protection, Face Shield, Chaps, Stihl Helmet system for forestry use
Concrete Saw ➡	Gloves, Hearing Protection, Face Shield,
Grinder ➡	Gloves, Hearing Protection, U.S Safety Double Matrix Face Shield,Leather forearm sleeves
Vibratory Plate ➡	Gloves, Hearing Protection
Jumping Jack ➡	Gloves, Hearing Protection
Remote Control Rollers ➡	Hearing Protection, Gloves
Welder ➡	Welding Gloves/Hood (with #10-14 shaded lens), Hearing Protection, Leather jacket/FR jacket/sleeves or apron Fire Watch-same protection if exposed
Torch Cutting ➡	Leather Gloves, #5 Goggles & Face Shield. Hearing Protection, Leather jacket/FR jacket/sleeves or apron. Fire Watch-same shaded lens
Manlift ➡	Full Body Harness & Lanyard
Shark Steam Cleaner, Pressure Washer ➡	Gloves, Hearing Protection, Face Shield
Jump Pack (battery jumping) ➡	Gloves, Face Shield
Working within a roadways right-of-way ➡	Orange safety vests or acceptable orange colored clothing. With reflective tape ie ( t-shirts or sweatshirts during daylight and clear weather)
Cutting knives ➡	Cut resistant gloves made with kevlar fibers.
Plasma Arc Cutting ➡	Leather Gloves, Eye Protection (See Table 1 in Manufacturers Manual) & Face Shield. Hearing Protection, Leather jacket/FR jacket/sleeves or apron. Fire Watch-same shaded lens
Handling Chemicals ➡	Consult MSDS for proper PPE
Wet Concrete ➡	Make washing facilities available use a pH-neutral or slightly acidic soap or buffered solution, Butyl or nitrile gloves, waterproof boots, When kneeling on wet cement use dry kneeboards. Use face shields when splattering cannot be controlled
Weed Trimmers ➡	Gloves, Nylon string or attachment (no metal), Hearing Protection,Stihl Helmet system for forestry use
Vacuum Excavators ➡	Leather/Rubber Gloves, Double Hearing Protection, Faceshield
Conveyor Truck ➡	Face Shield, Gloves